



Apparel Downproof Fillproof Evaluation (Rotating Box)

Client: XYZ Company

IDFL #: 13-123456

Item Tested: **Women's Jacket (Medium) Fall 2013**

Surface Area (cm²): 4,042
Stitch Lines (Linear Length cm): 444
Filling Used: 80/20 Down

Summary of Before & After Wash

Before Washing:	Outer Shell: Appoximately 33 Particles (fibers/feathers) escaped
	Inside Out: Appoximately 26 Particles (fibers/feathers) escaped
After Washing:	Outer Shell: Appoximately 52 Particles (fibers/feathers) escaped
	Inside Out: Appoximately 43 Particles (fibers/feathers) escaped

Particles evaluated after 15 and 30 minutes of tumbling

Source of Leakage

Leakage from the Fabric: *One third of the leakage is from the fabric.
Leakage from the Inter-panel Seam: *One third of the leakage is from the seams.
Leak from Stitch Lines: *One third of the leakage is from the stitch lines.

RATING† (5 Excellent, 4 Good, 3 Average, 2 Poor, 1 Bad)

Before Washing: **4**

After Washing: **3**

IDFL LABORATORY AND INSTITUTE

Certified Laboratory: IDFB • EDFA • DPSC Member: AATCC • ADFC • ASTM • CFDIA • EDFA • IABFLO

© 2011 IDFL

www.idfl.com

IDFL

Salt Lake City, Utah
info@idfl.com

IDFL EUROPE

Frauenfeld, Switzerland
europe@idfl.com

IDFL ASIA

Hangzhou & Taipei
asia@idfl.com